Diagram #2

Bracket Centerline

1 3/4"

Optional 2 ½" hole for 2" rigging hose sleeve through transom, Locate within hatched areas preferably above water line

2"

3"

Internal Stringer - No Access!

9"

● = Suggested locations for ½" mounting bolts